National Transportation Safety Board		NTSB	ID:	ANC90LA00	1	Aircraft	Aircraft Registration Number: N9382F		
FACTUAL REPORT		Occurr	rence	Date: 10/01	/1989	Most C	ost Critical Injury: None		
AYIATION ETYBON		Occurr	rence	Type: Accid	lent	Investiç	gated By	r: NTS	В
Location/Time									
Nearest City/Place	State		Zip	Code	Local Time	Time Z	one		
KING SALMON	AK		996	613	1747	ADT			
Airport Proximity: Off Airport/Airstrip	Dista	nce Fron	n Lar	nding Facility:	0	Direct	tion From	n Airpor	t: 0
Aircraft Information Summary									
Aircraft Manufacturer				Model/Series	3				Type of Aircraft
CESSNA				208					Airplane
Sightseeing Flight: No			Air	· Medical Tr	ansport Flight:	No			
Narrative									
Brief narrative statement of facts, conditions and circumstan	ices pert	inent to the	e accid	dent/incident:					

FACTUAL REPORT - AVIATION

Page 1

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC90LA001

Occurrence Date: 10/01/1989

AVIATION		Occii	rrence Tyne	e: Accident							
"ETY BOR"	formation	Occu	тепес турс	2. Accident							
Landing Facility/Approach In  Airport Name	iormation		Airport ID:	Airport Flove	tion	Dun	way Used	Pupur	av Longt	h T	Runway Width
Allport Name		- 1	Airport ID: NONE	Airport Eleva	. MSL		way Useu	Kuliwa	ay Lengt	.11	Rullway Width
			INOINE	F1	. IVISL						
Runway Surface Type:											
Runway Surface Condition:											
Type Instrument Approach: NONE											
VFR Approach/Landing: None											
Aircraft Information											
Aircraft Manufacturer				l/Series						Numbei	•
CESSNA			208						2080	0035	
Airworthiness Certificate(s): Norm	al										
Landing Gear Type: Float											
Homebuilt Aircraft? No	Number of Seats:	10	Certifie	ed Max Gross W	/t.		8000	LBS	Numbe	er of Eng	gines: 1
Engine Type: Turbo Prop			Engine M	anufacturer:			Model/Se PT6A-1				Rated Power: 600 HP
- Aircraft Inspection Information											
Type of Last Inspection			Date of La	st Inspection		Time Si	nce Last Insp	ection		Airfram	e Total Time
AAIP			09/23/19	89				23 H	ours		1436 Hours
- Emergency Locator Transmitter (	ELT) Information										
ELT Installed? Yes	ELT Opera	ted? No			ELT	Aided in	n Locating Ad	ccident S	Site? No	)	
Owner/Operator Information											
Registered Aircraft Owner			Street	Address 4100 WF	ST II	NTERN	ATIONAL F	ROAD			
MARK AIR, INC			City							State	Zip Code
				ANCHO	RAGE					AK	99502
Operator of Aircraft			Street	Address P.O. BO	X 701	ın					
MARK AIR EXPRESS			City	1.0.00	7(10					State	zip Code
WINTER THE EXT TREES				BETHEL						AK	99559
Operator Does Business As:						Op	perator Desig	nator Co	ode: HE	RA	
- Type of U.S. Certificate(s) Held:											
Air Carrier Operating Certificate(s)	: Commuter Air C	arrier; (	On-deman	d Air Taxi							
Operating Certificate:				Operator (	Certific	cate:					
Regulation Flight Conducted Unde	r: Part 135: Air Ta	axi & Co	ommuter	•							
Type of Flight Operation Conducted	d: Unknown										
		EACTI	IVI DEDU	ORT - AVIAT	ION						Page 2
		TACI	AL KEP	JKI - AVIAI	UN						i aye z

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC90LA001

Occurrence Date: 10/01/1989

AVIA	FION 30		Occurrent	ce Type: Acc	cident						
First Pilot Information	1										
Name				-	City			State	Dat	te of Birth	Age
On File					On File			On File	Oı	n File	35
Sex: M Seat Occupi	ed: Left	Pri	ncipal Profes	sion: Civilian	n Pilot		Cer	tificate Nu	mber:	On File	
Certificate(s): Fli	ght Instructor	; Commercia	al								
Airplane Rating(s): Mo	ulti-engine La	nd; Single-e	ngine Land	; Single-eng	ine Sea						
Rotorcraft/Glider/LTA: He	elicopter										
Instrument Rating(s): Ai	rplane										
Instructor Rating(s): He	elicopter										
Type Rating/Endorsemen	t for Accident/Ir	ncident Aircra	ft? No		С	urrent Bier	nial Flight R	Review?			
Medical Cert.: Class 2	Medica	al Cert. Statu	s: Valid Med	dicalw/ wai	ivers/lim.		Date of La	ast Medica	I Exan	n: 02/02/19	89
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Inst Actual	rument Simulated	Rotorcra	aft	Glider	Lighter Than Air
Total Time	3020	310	2870	40	140	7:	5 8	5	110		
Pilot In Command(PIC)	2765	305	2684	15	115	2	5		55		
Instructor											
Last 90 Days	210	210	210								
Last 30 Days	84	84	84								
Last 24 Hours	5	5	5		<u> </u>		10.11			157.40.11	
Seatbelt Used? Yes	Shou	ılder Harness	Used? Yes		Toxico	ology Perfo	rmed? No		Seco	nd Pilot? No	1
Flight Plan/Itinerary											
Type of Flight Plan Filed:	Company VF	R									
Departure Point					State	Air	oort Identifie			e Time	Time Zone
Same as Accident/Inci	dent Location							000	)0		
Destination					State	Air	oort Identifie	er			
KING SALMON					AK	Ar	(N				
Type of Clearance: Non	е										
Type of Airspace: Clas	s G										
Weather Information											
Source of Briefing: Fligh	nt Service Sta	tion									
Method of Briefing:											
			FACTUAL	REPORT -	AVIATIO	N					Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC90LA001

Occurrence Date: 10/01/1989

	AVIATION		С	ccurrenc	e Type:	: Accider	nt					
Weather	Information											
WOF ID	Observation Time	Time Zone	Wo	F Elevati	on	WOF D	istance Fr	om Acci	dent Site		Direction From Ac	cident Site
	0000			0 Ft.	MSL				0 NM			0 Deg. Mag.
Sky/Lowes	st Cloud Condition: Sca	ttered					6000 Ft. A	AGL	Condition of	f Ligh	nt: Day	
Lowest Ce	eiling: None			0 Ft.	AGL	Visib	ility:	100	SM	Altii	meter:	"Hg
Temperatu	ure: 7 °C	Dew Point:		°C	Wind	Direction	: Variable		<u> </u>	Der	nsity Altitude:	Ft.
Wind Spee	ed: 15	Gusts: 2	20		Weat	her Condt	tions at Ac	cident S	ite: Visual C	Cond	itions	
Visibility (F	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensit	y of Precip	oitation:	Unknown			
Restriction	ns to Visibility: None											
Type of Pro	ecipitation: None											
Accident	Information											
Aircraft Da	mage:		Ai	rcraft Fire	e:				Aircraft Exp	losio	n	
Classificati	ion:											
- Injury Su	mmary Matrix	Fatal	Serious	Mino	ır	None	TOTAL		<del>.</del>			
First Pi	ilot					1		1				
Second	d Pilot											
Studen	nt Pilot											
Flight I	nstructor											
Check	Pilot			1				7				
Flight E	Engineer							$\neg$				
Cabin A	Attendants			1				$\neg$				
Other 0	Crew			†				7				
Passer	ngers			$\top$	$\neg$	2		2				
- TOTAL A	ABOARD -			$\top$	$\neg$	3		3				
Other C	Ground	0		0	0			0				
- GRANE	D TOTAL -	0		0	0	3		3				

TRANSP	
National Transportation Safety Board	l
0 7	
FACTUAL REPORT	

NTSB	ID.	ANC901	Ann <sup>2</sup>

FACTUAL REPORT	Occurrence Date: 10/01/1989
AVIATION	Occurrence Type: Accident
Administrative Information	
Investigator-In-Charge (IIC)	
JAMES D. LA BELLE	
Additional Persons Participating in This Accide	nt/Incident Investigation: